

01/2022 EGYPT – Mediterranean Sea – Abu-Qir Port. Buoyage.

Source: EGYPTIAN Navy Hydrographic Department (ENHD)

Chart M12 [previous update 02/2021], WGS84 Datum

Insert	Starboard hand lateral buoy, with topmark, Light, Green, <i>Fl.4s</i> ,	(a)	31 ° 22.30'N, 030 ° 05.98'E
	Port hand lateral buoy, with topmark, Light, Red, <i>Fl.4s</i>	(b)	31 ° 22.25'N, 030 ° 06.18'E
Move:	Port hand lateral buoy	Fl R 4s From:	31 ° 21.57'N, 030 ° 05.91'E
		<i>To:</i>	31 ° 21.57'N, 030 ° 05.95'E
	Starboard hand lateral buoy	Fl G 4s From:	31 ° 20.83'N, 030 ° 05.54'E
		<i>To:</i>	31 ° 20.86'N, 030 ° 05.53'E
	Port hand lateral buoy	Fl R 4s From:	31 ° 20.81' N, 030 ° 05.68' E
		<i>To:</i>	31 ° 20.82' N, 030 ° 05.71' E
	Starboard hand lateral buoy	Fl G 4s From:	31 ° 20.06'N, 030 ° 05.28'E
		<i>To:</i>	31 ° 20.00'N, 030 ° 05.25'E
	Port hand lateral buoy	Fl R 4s From:	31 ° 20.04'N, 030 ° 05.44'E
		<i>To:</i>	31 ° 19.98'N, 030 ° 05.39'E
Delete:	Dangerous rock, submerged	(a)	31 ° 21.89'N, 030 ° 06.07'E
	North Cardinal Buoy	(b)	31 ° 22.15'N, 030 ° 06.39'E

Chart M33 [previous update 04/2021], WGS84 Datum

Delete:	Dangerous rock, submerged	(a)	Above
	North Cardinal Buoy	(b)	Above